


# PA Inside Diameter Air Probe

**PA Inside Diameter Air Probe** Mainly used for through hole measurements, the PA is a non-contact style sensor which shoots air through its orifices against a work object. The nozzle is at 8 to 20 mm from the tip of the probe.



## Sensor Probe Dimensions

Size D	A	B	C	E	F	G
4 to 8 mm	3.4	8	20	12	13.9	90
8 to 11.5 mm	3.4	8	20	12	13.9	90
11.5 to 14 mm	6	15	45	12	13.9	90
14 to 24 mm	6	20	45	14	16.2	90
24 to 40 mm	6	20	45	17	19.6	90
40 to 50 mm	6	20	50	21	24.3	110
50 to 65 mm	6	20	50	21	24.3	110
65 to 100 mm	8	20	50	26	30.0	110