


POR (Ring Type) Outside - Diameter Sensor

POR (Ring Type) Outside - Diameter Sensor. A type of measurement in which a workpiece is inserted into the ring. Typically used when workpieces are smaller.



Sensor Probe Dimensions

Size D	A	B	Chart
4 to 8 mm	50	20	1
8 to 14 mm	50	20	2
14 to 20 mm	50	20	
20 to 30 mm	60	22	
30 to 40 mm	75	25	
40 to 50 mm	85	28	
50 to 60 mm	100	30	
60 to 70 mm	112	30	